

Ingenuity at Dalplex



Late January there was a leak located in one of the roof air handling units that is critical to keep the roof from overloading with snow and caving in.

A team of steamfitters, instrument mechanics and welders sprung into action to identify, repair, and test the steam coil. The location of the work and scope of repair made this a very difficult job. This issue was a first of its kind as far as I am aware for Dalhousie. The ingenuity and teamwork of the group led to a safe and successful repair of the coil kept the roof in place, and allowed full return to operations at the field house.

Chad MacLellan
Greg Smith
Chelsey Coleman
Anton Hovorov

David Studley Bryan Nielsen Matt Goodwin Tim Hubley

Breton MacEachernUtilities Manager

Facilities Management