

Faculty of Engineering

Improvement of Technical Safety Inspection Process



Group #9 Guanjie Liu Haoran Mo Guanzhen Zhao Maiqi Li


Project Background

- The Technical Safety Division is one of the divisions of Nova Scotia Labor and Advanced Education
- Technical Safety Division currently has three divisions: Boilers and Pressure Department (BPD), Elevators and Lifts Department (ELD), and Fuel Safety Department (FSD)
- Technical Safety does all the mechanical safety inspections in Nova Scotia
- Some jobs cannot be finished on time

Scope of Work


- Data Analysis
- Scheduling Tool Development
- Workload Balance
- Workflow Improvement

Data analysis



- Fuel Safety Department
 - Incomplete Data
 - Time spent work on paper
 - Able to finish required jobs and handle additional 35% jobs with current capacity and efficiency





- Boiler Pressure Department
 - Imbalanced workload
- Able to handle 7299 inspections per year with current 9 inspectors.
- Able to finish required jobs with current capacity and efficiency

Elevator Lift Division

- Unable to finish current jobs
- Able to handle 1141 inspections per year with current 3 inspectors
- Additional inspectors or innovation are necessary to meet the requirement

Scheduling Tool

Scheduling Method


Header Exists Choose Task Type List

Header Exists Choose Task List

Greedy Algorithm


Input

- Inspection information
- **NSIN** number
- Address
- Coordinate
- Inspection type
- Deadline
- Inspection type and estimated time
- Inspector number



Scheduler.jar

Current Process



Task Type List Filepath

Output

- Each inspector has his own task list person.0.csv



- Output includes: NSIN number


Address

Inspection type

Deadline

Date

Improved Process



Scheduling Improvement

	Completed inspections in 2018	Uncompleted inspections in 2018	Completed inspections after applying the solution plan
ELD	690	1108	1050
BPD	3600	3315	7266
FSD	220	19	297

Acknowledgment

Data Entry and Reporting Improvement

		Completed inspections in 2018	Completed inspection s after applying the solution plan	Completed inspections after using software automatic update data
	ELD	690	1050	1108
	BPD	3600	7266	7600
	FSD	220	297	419

The team thanks the employees of the N.S. Technical Safety Division for their assistance, and appreciates the guidance of our supervisor, Dr. Ron Pelot, and other members of the IENG Department.