## Dalhousie University, Department of Facilities Management Confined Space Inventory Form

## Location: Behind NE corner of Dalplex. Room Number: N/A Date: August 22, 2013 Confined Space No: <u>DAL – SC – 01</u> Confined Space Class: \_\_\_\_\_ Description of Space: This is a service chamber (SC) situated in a ditch at the NE corner of Dalplex. The confined space contains electrical and communication lines. Construction Material: Concrete with a steel manhole cover. No. of Access / Egress Points: 1 Method of Entry: Ladder required. Dimensions of Access / Egress Opening: Diameter: 28.0 inches Type of Work Normally Conducted in Space: Maintenance or replacement of electrical and communication lines. Frequency of Work Performance: As required. Reference Atmospheric Testing: CO \_\_\_\_\_ ppm H<sub>2</sub>S \_\_\_\_\_ ppm O<sub>2</sub> \_\_\_\_\_ % LEL \_\_\_\_\_ Other:

Potential Hazards		
List all hazards near the access / egress opening(s) or in the confined space that must be controlled to ensure employee safety.		
Potential Hazards	Recommended Control Measures	
Oxygen Hazard:		
Reduced oxygen levels.	Sample for oxygen levels and ventilate	
Electrical Hazards:		
Electrical		
Mechanical Hazards:		

Physical Hazards:		
Chemicals Hazards:		
Biological:		
Additional Comments:		
Stairs House is in the background of Photo: 2013 – 08– 22 (1207)		

## Photographs






Photo Number: <u>2013 – 08 – 22 (1207)</u>

<u>2013 – 08– 22 (1207)</u>

List Emergency Procedures:		
Assessment Conducted By:	Signature:	
DI I	D .	
Phone number:	Date:	