

Wading into one of the messiest jobs on campus

Zone 1 plumber **Trevor Robinson** took on one of the messiest jobs on campus when the main vacuum tank at the Dental Clinic stopped working in November. The contents from each of the suction hoses that are used in patients' mouths during procedures all run into one big vacuum tank. When all the suction hoses stopped working at once, the clinic had to stop all procedures.

Zone 1 Supervisor **Perry Sabean** and Trevor Robinson went to the emergency hatch in the tank to identify the problem. Trevor had to wear a Tyvex suit and respirator to get far enough into the tank to fix the problem. Within just a few hours the team had everything repaired, the clinic was back up and running, and Trevor went home to take a very long shower.



Trevor Robinson poses beside the Dental Clinic vacuum tank

